ACTION PLAN

Burford-Charlbury

Site ID	Site	IMD 10% bands (1 = most	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
7	Burford Recreation Ground, Burford. OX18 4HU	deprived) 8	Football	Parish/Town Council	Burford Mayor notes that pitches poor; Pavilion is basic – no inside toilets, no hot water/showers; needs upgrade/replacement. One adult 11v11 pitch of basic quality; Two 9v9 pitches - one basic and one poor quality, and one poor quality 5v5 pitch. The adult pitch is played to capacity at peak time whilst the mini pitches have one MES of actual spare capacity.	Support Parish Council to improve ancillary provision onsite. WODC Leisure to engage with OFA and Mayor Burford to progress issues.	Council FF/OFA BE	Local Site	M	S	L	Protect Enhance
			Bowls		undertaken in 2023. One good quality flat bowling green that has capacity for additional members. Burford Town BC has plans to improve the kitchen, windows and heating in the clubhouse onsite.	Sustain green quality through dedicated maintenance regime. Support the Club to improve ancillary provision onsite.			L	L	L	
8	Burford School Cheltenham Road, Burford.	8	Rugby union	School	Two poor (M0/D1) quality senior rugby union pitches which are available for community use but played to capacity through school use.	Improve pitch quality to better accommodate curricular demand.	School RFU ECB/OCB FF/OFA	Local Site	L	L	L	Protect Enhance Provide
	OX18 4PL		Cricket		One cricket square with seven grass wickets which is unavailable for community use. Club seeking to refurbish the outdoor nets due to being unsafe; funding required.	Improve square quality to better accommodate curricular demand. Support school to refurbish nets.			L	L	L	
			3G pitch		3G built 2022; community use agreement in place. Additional access or improvement to ancillary provision may also be required to support additional use of the site.	Ensure the provider has in place a mechanism for future sustainability, such as a sinking fund formed over time, for repair and resurfacing of a potential new 3G pitch when necessary. Ensure 3G registration is maintained so that the pitch can continue to support use for competitive match play. Improve quality and access to ancillary facilities to service a potential new 3G pitch if required. WODC Leisure to engage with Burford School to clarify sinking fund measures. WODC Leisure to obtain details of Community Use Agreement.						
16	Chadlington Bowling Club,	7	Bowls	Sport Club	One standard quality flat bowling green. Chadlington BC reports it has plans to improve the green. It is currently operating below capacity but	Improve green quality through enhanced maintenance regime. Support the Club to improve green quality and add additional members.	Sport Club BE	Local Site	M	S	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Chipping Norton. OX7 3LY				expects to be within the recommended capacity range after future demand.							

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
17	Chadlington Sports Club Chapel Rd, Chadlington, Chipping Norton. OX7 3NA	7	Football	Sport Club	One youth 11v11, one youth 9v9, one mini 7v7 and three mini 5v5 pitches, all of standard quality. The youth 11v11 pitch is played to capacity and the youth 9v9 is played to capacity at peak times. Mini pitch formats have actual spare capacity of one MES per week. Chadlington FC indicates toilet and shower facilities onsite are outdated and in need of replacement. Pitch Power Assessment last undertaken 2020.	Improve pitch quality through enhanced maintenance regime. Explore the feasibility of improving toilet and shower facilities onsite. OFA to encourage Chadlington Sports Club to undertake a Pitch Power assessment.	Sport Club FF/OFA ECB/OCB	Local Site	L		L	Protect Enhance
			Cricket		One good quality cricket square with nine grass wickets and a non-turf pitch. The square has actual spare capacity at all times. Club withdrew from the Cherwell League in 2023.	Sustain square quality through dedicated maintenance regime. Oxfordshire Cricket will commence discussions with other cricket clubs and try to protect cricket provision, while exploring options for usage.			L	L	L	
18	Charlbury Bowling Club 74 Ticknell Piece Rd, Charlbury, Chipping Norton. OX7 3TW	10	Bowls	Sport Club	One excellent quality flat bowling green. Charlbury BC extended their Clubhouse in summer 2023 to facilitate short mat bowling indoors. Extension for the meeting room is planned but requires funding.	Sustain green quality through dedicated maintenance regime.	Sport Club BE	Local Site	L	L	M	Protect Enhance
19	Charlbury Cricket Club Dyers Hill, Charlbury,	10	Football	Sport Club	Two standard quality mini 7v7 pitches and one 5v5 pitch marked on a cricket outfield. The pitch is played to capacity at peak times.	Improve pitch quality through enhanced maintenance regime.	Sport Club FF/OFA ECB/OCB	Local Site	L	L	L	Protect Enhance
	Chipping Norton. OX7 3QG		Cricket		Two standard quality cricket squares, each with nine grass wickets and a nonturf pitch. Club have new outdoor nets. Only one square has capacity for additional play on Saturdays whilst both squares have capacity on Sundays and midweek. Club have recently gained funding for one non turf pitch, they require an additional non turf pitch to help with capacity.	Improve square quality through enhanced maintenance regime. Support Club to obtain funding for additional non turf pitch.			L	L	L	
23	Church Rise Playing Field, Finstock, Chipping Norton. OX7 3DH	10	Football	Parish/Town Council	One standard quality adult football pitch which remains unused.	Protect site for future football provision. Improve pitch quality through enhanced maintenance regime. WODC Leisure to engage with Parish Council regarding use of pitch and requirement for pitch improvements.	Council FF/OFA	Local Site	L	S	L	Protect Enhance
24	Churchill Playing Fields,	7	Football	Parish/Town Council	One standard quality mini 7v7 pitch which remains unused.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA ECB/OCB	Local Site	L	S	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Off Ticknell Place Rd, Charlbury,	<u> черпуеч</u>)				WODC Leisure to engage with Parish Council regarding use of pitch and requirement for pitch improvements.						
	Chipping Norton. OX7 3TP		Cricket		One standard quality cricket square with six grass wickets which remains unused.	Improve square quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. WODC Leisure to engage with Parish Council regarding use of pitch and			L	W	L	
35	Fifield Memorial Recreation Ground, Off Church Street, Fifield, Chipping Norton. OX7 6HE	9	Football	Parish/Town Council	One standard quality adult football pitch which remains unused.	requirement for pitch improvements. Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. WODC Leisure to engage with Parish Council regarding use of pitch and requirement for pitch improvements.	Council FF/OFA	Local Site	L	S	L	Protect Enhance
48	Kingham Hill School. Kingham,	6	Rugby Union	School	Five good quality junior rugby union pitches which are played to capacity through curricular use.	Improve pitch quality through enhanced maintenance regime.	School RFU EH	Local Site	L	L	L	Protect Enhance
	Chipping Norton OX7 6TH		Sand based AGP		One poor quality small size hockey suitable AGP which has sports lighting and available to the community. Club usage limited to training.	Improve pitch quality through resurfacing and enhanced maintenance regime. WODC Leisure to engage with school regarding Community usage.	EII		L	L	L	
49	Kingham Playing Field (Recreation Ground) New Road, Kingham, Chipping Norton OX7	6	Football	Parish/Town Council	One standard quality adult football pitch with actual spare capacity of one MES per week.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA to encourage Parish Council to undertake a Pitch Power assessment.	Council FF/OFA	Local Site	М	W	L	Protect Enhance
50	Leafield Playing Field. Lower End, Leafield, Witney OX29 9QJ	9	Football	Parish/Town Council	One standard quality adult football pitch and one 7v7 pitch with actual spare capacity of one MES per week. Club's temporary planning for portacabins expires Apr 2024 but needs long- term changing solution otherwise club will be expelled from competitions/league. Club to apply for temporary planning for portacabin while long term solution to changing room issue is found. Pitch Power Assessment last undertaken 2023.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA and WODC Leisure to support Club to find permanent changing solution.	Council FF/OFA	Local Site	M	S	L	Protect Enhance Provide
54	Nine Acres Recreation Ground (w/Charlbury Community Centre)	9	Football	Parish/Town Council	One adult 11v11, one 9v9 and one 5v5 pitch, all of good quality. Pitches have actual spare capacity of one MES per week. Pitch improvements as identified in 2020 LFFP have been undertaken.	Maximise spare capacity to alleviate overplay of other pitches in the area. Explore the feasibility of providing a 3G pitch onsite to alleviate identified training shortfalls.	Council FF/OFA LTA	Local Site	Н	М	Н	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Charlbury, Chipping Norton. OX7 3PQ				Pitch Power Assessment last undertaken 2021.	OFA to encourage Parish Council/Club to undertake a Pitch Power assessment.						
			Tennis		Four good quality macadam tennis courts that have sportslighting. The LTA reports that Charlbury TC has a long-term aspiration to refurbish the courts onsite into an all-weather, multi-sport surface with sportslighting. The Club is currently in the initial scoping phase for this and is looking to attract funding to support the development. In the short-term, the Club is looking to deep clean and repaint the existing courts.	Sustain court quality through dedicated maintenance regime. Examine the feasibility of converting the courts onsite to a multi-sport surface.			L	L	L	
59	Ramsden Tennis Club, Akeman Street, Chipping Norton. OX7 3BJ	8	Tennis	Sport Club	One standard quality macadam tennis court which is available for community use but without sports lighting.	Improve court quality through enhanced maintenance regime.	Sport Club LTA	Local Site	L	L	L	Protect Enhance
62	OX7 3BJ Shipton Under Wychwood Recreation Ground, 2 Meadow Close, Shipton-	10	Football	Parish/Town Council	One standard quality adult football pitch with 0.5 MES of actual spare capacity.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA to encourage Parish Council to undertake a Pitch Power assessment.	Council FF/OFA LTA	Local Site	М	S	L	Protect Enhance
	under- Wychwood, Chipping Norton. OX7 6BY		Tennis		Three standard quality artificial tennis courts that are available for community use but without sports lighting. Wychwood TC aspires to install a clubhouse onsite and urgent need for sportslighting to deal with significant overplay remains. Planning application for sportslighting rejected in October 2022.	Improve court quality through enhanced maintenance regime. Support planning application for sportslighting to increase court capacity onsite, to enable Wychwood TC to operate within the recommended capacity.			Н	M	M	
63	Shipton Under Wychwood Cricket Club. High Street, Shipton- under- Wychwood. Chipping. Norton OX7 6DG	10	Cricket	Sport Club	Two good quality cricket squares with 16 and 11 grass wickets respectively. Both squares are played to capacity on Saturdays although have capacity on Sunday and midweek. In Feb 24 a tree fell on tearoom making it unusable so urgent need for new teahouse/ clubhouse; Club seeking quotes. If acceptable will take plans through the planning process with the aim of getting construction underway in the autumn/winter 2024. Club undertaking significant fundraising. Plans to convert Pavilion bar area into changing rooms for women/girls, install a disabled toilet etc. Club seeking a grant from the ECB to help with this.	Sustain square quality through dedicated maintenance regime. Support Club to improve ancillary facilities.	Sport Club ECB/OCB	Local Site	M	L	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
72	Stonesfield Playing Field 1 Field Close, Stonesfield, Witney. OX29 8HA	8	Football	Parish/Town Council	Two good quality youth 11v11 pitches of which one is overmarked on the cricket outfield. Two good 7v7 and one good 5v5 pitch. The pitches are played to capacity at peak times. Listed in the 2020 LFFP for ancillary facility improvements. Pitch Power Assessment last	Sustain pitch quality through dedicated maintenance regime. Improve ancillary facilities onsite in line with LFFP recommendations.	Council FF/OFA ECB/OCB LTA	Local Site	L	М	L	Protect Enhance
			Cricket		undertaken in 2023. One good quality cricket square with nine grass wickets. The square is played to capacity on Saturdays but has spare capacity on Sundays and midweek.	Sustain square quality through dedicated maintenance regime.	_		L	L L	L	
			Tennis		Three good quality artificial tennis courts which are available for community use but without sports lighting. Stonesfield TC are exploring costs to install sports lighting due to overplay. Planning application 23/02653/FUL approved in May 24. Stonesfield TC reports changing facilities onsite are in poor condition.	Sustain court quality through dedicated maintenance regime. Explore the feasibility of improving ancillary provision onsite. Support provision of sportslighting onsite to increase site capacity.			M	M	L	
73	Swinbrook Cricket Club The Crossroads, Swinbrook. OX18 4DX	8	Cricket	Sport Club	One good quality cricket square with eight grass wickets and a non-turf pitch. Used by Swinbrook CC, the square has capacity for an increase in demand at all times.	Sustain square quality through dedicated maintenance regime.	Sport Club ECB/OCB	Local Site	L	L	L	Protect
79	Memorial Playing Field, High Street, Ascott-under —Wychwood, Chipping Norton. OX7 6AW	10	Football	Parish/Town Council	One standard quality adult 11v11 pitch with one MES of actual spare capacity.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA to encourage Parish Council to undertake a Pitch Power assessment.	Council FF/OFA ECB/OCB	Local Site	М	S	L	Protect Enhance Provide
	OAT DAVV		Cricket		One good quality cricket square with six grass wickets which has spare capacity at all times. Ascott-under-Wychwood CC is searching for funding for roll-on covers so that better quality wickets can be prepared onsite and fewer matches lost due to rain. The club is growing and is gradually investing in equipment to maintain the ground. Club looking to create 2 artificial cricket nets.	Sustain square quality through dedicated maintenance regime. Support provision of wicket covers onsite. Oxfordshire Cricket to support the Club to provide a junior section.			L	L	L	
81	Milton-Under- Wychwood	9	Football	Parish/Town Council	One standard quality adult football pitch which is played to capacity.	Improve pitch quality through enhanced maintenance regime.	Council FF/OFA	Local Site	L	L	L	Protect Enhance
	Village Green, 24 Shipton Road, Milton- under-		Tennis		The one Tennis court has a new carpet surface. Court is available for community use but without sportslighting.	Improve court quality through enhanced maintenance regime.	LTA		L	L	L	

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Wychwood, Chipping Norton. OX7 6JP											

Carterton

Site ID	Site	IMD 10% bands (1 = most	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
1	Aston Village Playing Field Cote Road, Aston, Bampton. Ox18 2FS	deprived) 10	Football	Trust	One poor quality adult 11v11 pitch which is overplayed by 3.5 MES per week. One 9v9, one 7v7and one 5v5 all in poor condition. Aston FC is looking to improve overall pitch quality onsite to accommodate increased demand. Pitches are reported to drain poorly and be maintained insufficiently by the Trust that owns the site. Changing facilities are outdated; the Club are working to construct a dedicated clubhouse facility onsite. Aston Community Trust plan on constructing a MUGA (23/00948/FUL). Pitch Power Assessment last undertaken in 2023.	Improve pitch quality through enhanced maintenance regime to reduce overplay. Look to relocate some demand to an alternate site with spare capacity to alleviate overplay. Support provision of improved ancillary facilities onsite.	Trust FF/OFA	Local Site	Н	S	M-H	Protect Enhance Provide
3	Bampton Recreation Ground. 9 Buckland Road, Bampton. OX18 2AA	10	Football	Community Organisation	Two 11v11 Adult standard quality football pitches with 0.5 MES of actual spare capacity. Three junior 11v11, one 9v9 and one 7v7 – all of standard quality.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA to encourage Bampton Parish Council to undertake a Pitch Power assessment.	Community FF/OFA ECB/OCB LTA	Key Centre	М	S	L	Protect Enhance Provide
			Cricket		One standard cricket square with seven grass wickets and a non-turf pitch. Bampton in the Bush CC reports it struggles with the quality of the outfield and the length of grass. The square has capacity for two additional matches per season.	Improve square quality through enhanced maintenance regime. Support Bampton in the Bush CC to improve the outfield.			L	L	L	
			Tennis		Two standard quality macadam tennis courts that are without sportslighting. The site is currently overplayed by 87 members, with this expected to rise to 172 after future demand. Bampton Recreation Ground Trust are in advanced stages of planning to redevelop the site, including one additional tennis court, sportslighting on all three and a smart access gate entry system. Club have modest funds and will need external funding to support this development.	Improve court quality through enhanced maintenance regime. Support provision of sportslighting onsite to increase site capacity. Support redevelopment of the site.			M	L	M	
4	Bampton Town Football Club. Buckland Road, Bampton. OX18 2BW	10	Football	Sport Club	One 11v11 basic quality adult football pitch with one MES of actual spare capacity and one basic quality 7v7 pitch. Club keen to undertake improvements to Pavilion.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. Support enhancement of ancillary facilities.	Sport Club FF/OFA	Local Site	L	L	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
					Pitch Power Assessment last undertaken in 2023.							
10	Carterton ATP (Carterton Community College) Upavon Way, Carterton. OX18 1BU	9	3G pitch	College/ Leisure Trust	One standard quality, full-size 3G pitch which has sportslighting and is on the 3G Register. Pitch suffers from persistent vandalism and litter is often left on the playing surface following use. Despite being FA approved, there are no ancillary facilities onsite which limits match usage at weekends.	Improve pitch quality through enhanced maintenance regime. Ensure WODC has a Pitch Replacement Fund in place for repair and resurfacing when necessary. Ensure 3G registration is renewed when required so that the pitch can continue to support use for competitive match play. Explore feasibility to provide ancillary provision onsite.	College Leisure Trust FF/OFA	Key Centre	M	M	Н	Protect Enhance Provide

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
12	Carterton Community College	9	Football	College	One standard quality adult 11v11 football pitch which has discounted spare capacity due to unsecure tenure.	Improve pitch quality through enhanced maintenance regime.	College FF/OFA RFU	Local Site	L	L	L	Protect Enhance
	Upavon Way, Carterton.		Rugby union		One poor (M0/D1) quality senior rugby union pitch which is played to capacity through curricular demand.	Improve pitch quality through enhanced maintenance regime.	LTA		L	L	L	
	OX18 1BU		Tennis		Four poor quality macadam tennis courts that are without sportslighting and unavailable for community use.	Improve court quality through resurfacing and enhanced maintenance regime.			L	L	L	
11	Carterton Bowling Club, 122 Sycamore Drive, Carterton. OX18 3AU	6	Bowls	Sports Club	One good quality flat bowling green.	Sustain green quality through dedicated maintenance regime.	Sports Club BE	Local Site	L	L	L	Protect
14	Carterton Recreation Ground. Alvescot Road, Carterton. OX18 3JH	6	Football	Parish/Town Council	One poor quality adult pitch. Spare capacity is discounted due to poor quality. Site suffers from vandalism, litter, dog fouling and glass onsite. Ancillary provision onsite is rated as poor quality. Carterton Town FC and Siege FC indicate plans are in place to demolish the existing pavilion and replace it with an updated facility.	Improve pitch quality through enhanced maintenance regime. Support the clubs to provide improved ancillary provision onsite. OFA to encourage Carterton Town Council to undertake a Pitch Power assessment.	Council FF/OFA	Local Site	M	M	M-H	Protect Enhance
25	Clanfield 85 FC. Radcot Road, Clanfield. OX18 2ST	8	Football	Sport Club	One good quality 11v11 adult (stadia) football pitchsith actual spare capacity of three MES per week. A mini pitch overmarks one of the adult pitches. Clanfield (85) FC aspires to improve the clubhouse and changing facilities and is exploring the feasibility of installing a 3G pitch onsite.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. Explore the feasibility of improving ancillary provision onsite. Assess the viability of installing a 3G pitch onsite. OFA to encourage Clanfield 85 FC to undertake a Pitch Power assessment.	Sport Club FF/OFA	Local Site	M	L	Н	Protect Enhance Provide
28	Colston Lawn Tennis Club, Broadwell, Lechlade. GL7 3QS	6	Tennis	Sport Club	Six good quality macadam tennis courts of which three are serviced by sportslighting.	Sustain court quality through dedicated maintenance regime.	Sport Club LTA	Local Site	L	L	L	Protect

Site ID	Site	IMD 10% bands (1 = most	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
46	Kilkenny Football Ground, Kilkenny Lane, Carterton. OX18 1DY	8	Football	Sport Club	One adult 11v11 advanced quality pitch and one 9v9 poor quality pitch. The adult pitch is played to capacity whilst the youth pitch has 0.5 MES per week of actual spare capacity. Pitches at Kilkenny Football Ground are serviced by poor quality ancillary facilities; one room in the building has a collapsed roof and approximately half the seats in the stand are missing. The site is an identified priority project for football, notably for the replacement of the existing changing pavilion. Carterton Playing Fields has two adult pitches (one advanced; one basic condition), two 9v9 (one poor, one basic condition) one 7v7 in basic condition and four mini 5v5 pitches in basic condition. The two adult pitches are both overmarked with 9v9 pitches. No pitches are considered to have actual spare capacity due to unsecure tenure. The site neighbours a quarry, so stones come through the soil onto the pitches frequently. Despite this, they reportedly drain well, are adequately maintained and are considered to be of standard quality. The Club is in receipt of Football Foundation Grass Pitch Maintenance Fund support, awarded from 2021 onwards. Carterton FC currently has a rolling annual agreement with the developer	Protect the site given existing playing pitch capacity shortfalls evidenced by the PPS. Ensure that appropriate mitigating reprovision is able to meet Sport England Playing Fields Policy and secured for the benefit of community sport should discussions with developer come to fruition. In the short-term, improve pitch quality at both sites and secure tenure for the Club at Carterton Playing Fields until such time that an alternative proposal is accepted and pursued. Work with the Club to explore the potential to develop a sports hub and for this sports hub to have a full size 3G pitch to meet the Area shortfall for 3G pitches for affiliated football team training, most of which is expressed by Carterton FC and Carterton Town FC. Essential that 3G pitch is on the FA Register and that pitch replacement fund is put in place. Ensure the developer proposal can meet current NGB facility specification guidance and that new facilities are appropriate for the scale of demand and level of play. Ensure that any new sports hub has	Sport Club Private FF/OFA	Local Sites (potential Hub Site)	H	S-M	H	Protect Enhance Provide
96	Carterton FC, Carterton Playing Fields, Kilkenny Lane, Carterton OX18 1DY	8	Football	Private	for use of Carterton Playing Fields (adjacent to Kilkenny Football Ground) which does not provide long term security. Carterton FC has been in recent discussions with David Wilson Homes regarding the creation of a new sports hub to the north of the existing pitches at Kilkenny Football Ground, in replacement of proposed loss of playing field and facilities at both Kilkenny Football Ground and Carterton Playing Field. Current plans include the like-for-like provision of a Pavilion, pitches and car park. The Club would still need a full sized 3G pitch for which they require additional funding. A Steering Gp with Club, WODC, OFA, Football Foundation and SE input has been formed to take forward the 3G proposal. This Steering Gp will also	a football led governance model and that long-term tenure is secure at the site for Carterton FC, through either freehold or long-term leasehold. As part of this, explore opportunity for the future amalgamation of Carterton Town FC into Carterton FC, to develop one main club in the Carterton Area able to sustain and maximise use of a sports hub with a new and expanded facility offer.						

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
		черпчеч			discuss the developer proposal as detail emerges. Pitch Power Assessment last undertaken in 2023.							
53	Monahan Way Sports Pavilion (Carterton Pavilion), Brize Norton, Carterton OX18 3AN	8	Football		Two adult, one youth 9v9 and two mini 5v5 pitches all of poor quality. The adult and youth 9v9 pitches are overplayed by 4.5 and one MES per week respectively. The mini 5v5 pitches are played to capacity at peak times. Pitch quality is poor, with the pitches often freezing during the winter. Rabbit holes and animal fouling are prevalent onsite and pitches are frequently used by dog walkers and as a community space. Pitches listed in the 2020 LFFP for pitch improvements. Although 2023 STRI Report indicated significant pitch remediation is required, pitches are deemed safe to play on. Ancillary provision onsite is deemed to be of adequate quality but is underused. There are four changing rooms onsite; the Food Bank use the function use. Pitch Power Assessment last undertaken in 2021.	Improve pitch quality through enhanced maintenance regime to reduce overplay and in line with 2020 LFFP recommendations remediate grounds as necessary in accordance with 2023 STRI Report. Determine long term future use of site.	Trust FF/OFA ECB/ OCB	Local Site	M	8	M	Protect Enhance
			Cricket		One cricket square with eight grass wickets and a non-turf pitch. The square is in poor condition, is no longer maintained and is no longer used for formal cricket demand.	Although there is currently no demand for cricket at the site, the site should be protected in the short-term as strategic reserve and be available should there be demand to do so. Funding required to remediate area to bring up to playable condition.			-	-	-	Protect
57	RAF Brize Norton, Carterton. OX18 3LX	8	Football	MOD	Five adult 11v11 and one mini 5v5 pitch all of standard quality. Pitches are unavailable for community use. Possible that RAF may build over football pitches in the near term.	Sustain pitch quality for RAF use.	MOD FF/OFA ECB/ OCB	Local Site	L	L	L	Protect
			Cricket		One standalone non-turf pitch which is unavailable for community use.	Sustain pitch quality for RAF use.	RFU EH		L	L	L	
			Rugby Union		One poor (M0/D1) quality senior rugby union pitch which is unavailable for community use.	Sustain pitch quality for RAF use.	LTA		L	L	L	
			Sand based AGP		One small-size hockey suitable AGP of standard quality which have sports lighting but unavailable to the community.	Sustain pitch quality for RAF use.			L	L	L	
			Tennis		Three standard quality macadam tennis courts that are without sports lighting and unavailable to the community.	Sustain court quality for RAF use.			L	L	L	
66	St John The Evangelist CE Primary School, Bluebell	10	Hockey	School	One good quality small-size hockey suitable AGP which is available to the community but without sports lighting.	Sustain pitch quality through dedicated maintenance regime.	School EH	Local Site	L	L	L	Protect

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Way, Carterton. OX18 1JF											
71	Station Road Recreation Ground,	8	Football	Parish/Town Council	One standard quality adult 11v11 football pitch with one MES of actual spare capacity.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA ECB/OCB LTA	Local Site	М	S	L	Protect Enhance
	Brize Norton, Carterton. OX18 3PU		Cricket		One good quality cricket square with six grass wickets. Used by Minster Lovell CC, the square has capacity at all	Sustain square quality through dedicated maintenance regime.	LIA		L	L	L	
			Tennis		times. One poor quality macadam tennis court which is available for community use but without sportslighting. Work underway to extend Elderbank Hall. Parish Council awaiting quotes for new Sports Pavilion which will be constructed utilising s106 funds.	Explore feasibility of improving court quality through resurfacing/refurbishment. LTA keen to engage in conversations with Parish Council around online booking.			L	L	L	
100	Langford Cricket Club, The Wicket, Lechslade. GL7 3LS	6	Cricket	Sport Club	One standard quality cricket square with eight grass wickets. The square is overplayed by 18 matches per season. Ancillary facilities reported to be in poor condition. A new Pavilion (23/00513/FUL) is currently under construction. Langford CC has demand for both static and mobile training nets onsite.	Improve wicket quality onsite to reduce overplay. Explore the feasibility of providing a non-turf pitch onsite to alleviate overplay. Support the Club to improve ancillary facilities and provide training facilities onsite.	Sport Club ECB/ OCB	Local Site	L	L	M	Protect Enhance Provide

Chipping Norton

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
20	Chipping Norton Cricket Club, Banbury Road, Chipping Norton. OX7 5SX	10	Cricket	Sport Club	One good quality cricket square with 10 grass wickets, one non turf and one net. The square is played to capacity on Saturdays but has capacity on Sundays and midweek. Chipping Norton CC indicates facilities onsite do not meet ground requirements as there are only two changing rooms and no umpires changing room. Club has plans to redevelop showers, changing rooms to provide for girls, disabled and umpires but requires funding and support.	Sustain square quality through dedicated maintenance regime and ensure facilities onsite comply with ground grading regulations. Support the Club to enhance ancillary facilities.	Sport Club ECB/ OCB	Local Site	M	8	L	Protect Provide
21	Chipping Norton Leisure Centre, Burford	9	Sand based AGP	Trust	One small-size hockey suitable AGP which has sportslighting and is available for community use. The pitch was resurfaced in 2019 and is of good quality.	Sustain pitch quality through dedicated maintenance regime. Ensure pitch replacement fund is in place for refurbishment when necessary.	Trust EH FF/OFA LTA	Local Site	L	L	M	Protect
	Road, Chipping Norton. OX7 5DY		Tennis		Four good quality artificial tennis courts that have sportslighting and are available for community use. Courts are supported by good quality ancillary provision.	Sustain court quality through dedicated maintenance regime.			L	L	L	
	Chipping Norton Area		Football		2020 LFFP 2020 highlights requirement for 3G in Chipping Norton due to housing growth. Requirement omitted from 2022 PPS. Possible 3G location to be determined.	WODC/OFA to investigate. requirement and feasibility	Sport Club FF/OFA		Н	M	Н	Provide
30	Enstone Sports And Social Club, Braybrooke Close, Chipping.	9	Football	Sport Club	Two good quality adult 11v11 football pitches with actual spare capacity of 1.5 MES per week. Charlbury Town Youth FC and Enstone FC have plans to create a 3G pitch onsite.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. Assess the viability of installing a 3G pitch onsite.	Sport Club FF/OFA ECB/ OCB	Local Site	М	S	Н	Protect Provide
	Norton OX7 4AZ		Cricket		One standalone non-turf pitch of adequate quality which is not known to be used.	Sustain wicket quality through dedicated maintenance regime.			L	L	L	
38	Great And Little Tew Cricket Club, 6 new Road, Great Tew, Chipping Norton. OX7 4AG	6	Cricket	Sport Club	Two good quality cricket squares with 16 and six wickets respectively. Both squares have actual spare capacity at all times. Other Witney teams use the Tew second pitch.	Sustain square quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Sport Club ECB/ OCB	Local Site	М	S	L	Protect

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
39	Greystones, Burford Road, Chipping Norton. OX7 5UY	10	Football	Sport Club	One youth 11v11, one youth 9v9, one mini 7v7 and one mini 5v5 all of which are standard quality. The youth 11v11 and mini 7v7 pitches each have actual spare capacity of 0.5 MES per week. The youth 9v9 and mini 5v5 pitches are played to capacity at peak time. The site suffers from damage by rabbits. It is supported by standard quality ancillary facilities although these are said to be too far away from the youth 9v9 pitch.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. Support Chipping Norton Swifts to access the scout hut which neighbours the youth 9v9 pitch.	Sport Club FF/OFA RFU BE	Key Centre	M	S	L	Protect Enhance
			Rugby Union		Three senior, two junior and five mini pitches, all of good (M2/D1) quality. One senior pitch has sportslighting. The pitch with sportslighting is overplayed by one MES per week whilst remaining pitch types are all played to capacity at peak times. The Club have improved their external social space developing a larger well-constructed patio. Green, low-cost energy solutions will be required to ensure the building remains sustainable.	Sustain pitch quality through dedicated maintenance regime. Explore reallocating match and training demand to alleviate overplay of the senior pitch with sports lighting. Support the Club to provide increased sportslighting with backlighting to create a sports lit training area on site. Consider whether the Club could utilise s106/CIL funding for improvements due to considerable local housing growth.			Н	M	M-H	
			Bowls		One good quality bowling green used by Chipping Norton BC which operates within the recommended capacity range.	Sustain green quality through dedicated maintenance regime.			L	L	L	-
45	Jubilee Playing Field, Worton	8	Football	Community Organisation	One standard quality adult football pitch which is currently unused.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Community FF/OFA LTA	Local Site	М	S	L	Protect Enhance
	Road, Middle Barton,		Tennis		One poor quality macadam tennis court without sports lighting.	Improve court quality via enhanced maintenance regime/resurfacing.	- BE		L	L	L	
	Chipping Norton. OX7 7EE		Bowls		One good quality flat bowling green used by Middle Barton BC.	Sustain green quality through dedicated maintenance regime.			L	L	L	
60	Sandford Park Sandford St Martin, Chipping Norton. OX7 7AH	8	Cricket	Sport Club	One good quality cricket square with 16 grass wickets which has capacity on Sundays.	Sustain square quality through dedicated maintenance regime.	Cricket ECB/ OCB	Local Site	L	L	L	Protect
64	Soho Farmhouse. Great Tew, Chipping Norton. OX7 4JS	6	Tennis	Commercial Management	Four good quality macadam tennis courts that are available for community use but without sportslighting.	Sustain court quality through dedicated maintenance regime.	Commer- cial LTA	Local Site	L	L	L	Protect

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
82	Walterbush Road Ground, Chipping Norton. OX7 5DQ	4	Football	Sport Club	Disused site. Previously home to Chipping Norton Town FC; accommodated a single adult pitch but the Club had to relocate to Enstone Sports and Social Club after losing ownership of the site. The pitch has not been used or maintained since 2014.	The March 2024 Stage E Review decided that site should be retained and protected for the time being. This was reviewed again at the Steering Gp Strategy mtg in June 24 where it was noted that this site had not been used for many years, the land is overgrown and the PPS notes sufficient current and future adult pitch capacity in Chipping Norton. Therefore, it was decided that there was no longer a need to protect this site. However, should the site be released for development, the developer would need to provide either appropriate mitigating reprovision to a replacement site in order to address any shortfalls that may subsequently arise (such as replacing the sports pitch in an alternative location with ancillary provision), or a s106 financial contribution towards improvements and maintenances of other football pitches/other sporting grounds/clubs in the catchment area in order to benefit community sport. This decision is to be noted in an Addendum to the PPS.	Council FF/OFA	Local site		-		
102	Kitebrook Preparatory School, Moreton-in- Marsh. GL56 0RP	6	Tennis	School	Two standard quality macadam tennis courts that are unavailable for community use.	Improve pitch quality through enhanced maintenance regime.	School LTA	Local Site	L	L	L	Protect Enhance

Eynsham – Woodstock

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
5	Bartholomew School Pitches, Bartholomew Close, Eynsham. OX29 4QG	10	Football	School	One standard quality youth 9v9 pitch which is unavailable for community use.	Improve pitch quality through enhanced maintenance regime.	School FF/OFA	Local Site	L	L	L	Protect Enhance
6	Bartholomew Sports Centre, 52 Back Lane,	10	Cricket	Trust	One standard quality cricket square with eight grass wickets. The square is currently unused.	Improve square quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Trust ECB/ OCB FF/OFA	Local Site	М	S	L	Protect Enhance
	Eynsham. OX29 4QP		Sand based AGP		One standard quality, small-size, sand filled AGP which has sports lighting and available for community use.	Improve pitch quality through enhanced maintenance regime. Ensure pitch replacement fund is in place for refurbishment when necessary.	EH LTA		L	M	M	
		eassington 9 Foot	Tennis		Four standard quality macadam tennis courts which are without sportslighting.	Improve court quality through enhanced maintenance regime.			L	L	L	
15	5 Cassington Recreation Ground 30 Elms Road, Cassington, Witney. OX29 4DP	9	Football	Sport Club	One good quality adult football pitch with actual spare capacity of one MES.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Sport Club FF/OFA ECB/ OCB	Local Site	М	S	L	Protect Enhance
			Cricket		One good quality cricket square with six grass wickets that currently lies unused.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	LTA		М	S	L	
			Tennis		Two artificial tennis courts of standard quality that are available for community use.	Improve pitch quality through enhanced maintenance regime.			L	L	L	
27	Cokethorpe School Standlake Road, Witney.	10	Football	Independent School	Three adult, two youth 11v11, two youth 9v9, two mini 7v7 and two mini 5v5 pitches all of good quality. All pitches are unavailable for community use.	Sustain pitch quality for curricular use.	School FF/OFA ECB/ OCB	Local Site	L	L	L	Protect Enhance
	OX29 7PU		Cricket		Two cricket squares with ten and seven grass wickets respectively, both of good quality. The ten wicket square is used to capacity on Saturdays by Oxford Downs CC but has capacity on Sundays and midweek. The seven wicket square is used only for curricular demand.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	RFU		М	S	L	
			Rugby Union		Three senior and four junior pitches which are unavailable for community use. All pitches are considered to be poor (M0/D1) quality and played to capacity through curricular use.	Improve pitch quality through enhanced maintenance regime.			L	L	L	
			Hockey sand based AGP		Two standard quality, full size, sand based pitches without sportslighting. Both pitches were built in 2006. School has recently enquired about costs for resurfacing and were	Improve pitch quality through enhanced maintenance regime. WODC Leisure to seek assurances from Cokethorpe School that a pitch			М	S	L	

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
					signposted to Notts to carry out a pitch condition report. Pitches are not available for wider community use although Wychwood HC has a relationship with the School which allows the Club access at weekends for match play only. The Club trains at Wood Green School midweek due to the presence of sportslighting.	replacement fund is in place for repair and resurfacing when necessary. WODC/England Hockey to formally secure tenure for the Club if possible, or alternatively consider potential for relocation of all hockey activity to Wood Green School if booking space available at that site. WODC Leisure to confirm if preference of the school not to have sportslighting or due to planning condition.						
29	Combe Playing Field 4 Park Road, Combe, Witney. OX29 8NA	10	Football	Sport Club	One adult, one youth 9v9, one mini 7v7 and one mini 5v5 pitch all of standard quality. The adult pitch is played to capacity whilst the mini pitches are played to capacity at peak time. The youth 9v9 pitch has 0.5 MES per week of actual spare capacity.	Improve pitch quality through enhanced maintenance regime.	Sport Club FF/OFA ECB/ OCB	Local Site	L	L	L	Protect Enhance
			Cricket		One standard quality cricket square with eight grass wickets. Combe CC indicates the outfield onsite is in poor condition as it is used for football through the winter. The square has capacity on Saturdays, Sundays and midweek.	Improve square quality through enhanced maintenance regime.			L		L	
31	Eynsham Community Primary	9	Football	School	One standard quality mini 5v5 pitch which is unavailable for community use.	Improve pitch quality through enhanced maintenance regime.	School FF/OFA EH	Local Site	L	L	L	Protect Enhance
	School, Beech Road, Eynsham. OX29 4LJ		Sand based AGP		One poor quality, small-size, hockey suitable AGP which is available for community use but without sports lighting.	Improve pitch quality through resurfacing when feasibly possible. WODC Leisure to seek assurances that a pitch replacement fund is in place for repair and resurfacing when necessary			L	L	L	
32	Estelle Manor/ Eynsham Hall Sports Ground, North Leigh. OX29 6SL	9	Football	Sport Club	Two adult and one youth 9v9 pitch, all of standard quality. Both pitch formats have 0.5 MES per week of actual spare capacity. Club considering developing a 3G pitch.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Sport Club FF/OFA	Local Site	M	W	L	Protect Enhance
33	Eynsham Playing Field (North Side) 1 Oxford Road, Eynsham. OX29 4HG	9	Football	Community Organisation	Two adult 11v11 and one mini 5v5 pitch, all of good quality. Both pitch formats have one MES per week of actual spare capacity. The Sports Pavilion is aged and needs replacement. This requirement was omitted from the 2022 PPS.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA to encourage Eynsham Parish Council to undertake a Pitch Power assessment.	Community FF/OFA	Local Site	М	S	L	Protect
34	Eynsham Playing Field (South Side) 1 Oxford Road, Eynsham.	5	Football	Community Organisation	One adult 11v11 and one mini 7v7 pitch, both of good quality. The adult pitch is played to capacity at peak time whilst the mini pitch has 0.5 MES per week of actual spare capacity.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Commu-nity FF/OFA	Local Site	М	S	L	Protect

18

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	OX29 4HG					OFA to encourage Eynsham Parish Council to undertake a Pitch Power assessment.						
36	Freeland Playing Field, Pigeon House Lane, Freeland. OX29 8AG	10	Football	Parish/Town Council	One poor quality adult pitch which is played to capacity at peak time. Freeland FC working to improve pitch quality in line with recommendations made in the FA's PIP report onsite. Pitch often suffers from flooding in the winter months. Last Pitch Power assessment @12-18mths ago.	Improve pitch quality through enhanced maintenance regime. OFA to encourage Freeland Parish Council/Club to undertake a Pitch Power assessment.	Council FF/OFA ECB/ OCB	Local Site	L	L	L	Protect Enhance Provide
			Cricket		One standard quality cricket square with six grass wickets. It is not known what agreement Freeland CC has in place for access to the site. The Club is also without an onsite pavilion. The square is overplayed by 13 matches per season.	Improve square quality and outfield through enhanced maintenance regime to reduce overplay. Look to relocate some demand to an alternate site with spare capacity/install a non-turf pitch to alleviate overplay. Explore the feasibility of providing a pavilion onsite.			M	w	Н	

Site ID	Site	IMD 10% bands (1	Sport	Management	March 2024	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
טו		= most deprived)										
43	Hanborough Playing Fields, The Pavilion	10	Football	Parish/Town Council	One standard quality adult football 11v11 pitch with actual spare capacity of one MES per week.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA ECB/ OCB	Key Centre	L	S	L	Protect Enhance
	Roosevelt Road, Long Hanborough. OX29 8JG		Cricket		One good quality grass cricket square with six wickets. It is used by Hanborough CC and has actual spare capacity at all times.	Sustain square quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	LTA BE		L	S	L	
	C/120 00 C		Tennis		Parish Council note one good quality macadam tennis court with sportslighting (resurfaced 2015) lines recently repainted.	Sustain court quality through dedicated maintenance regime.			L	L	L	
			Bowls		One standard quality flat bowling green used by Hanborough BC. The green operates within the recommended capacity range.	Improve green quality through enhanced maintenance regime.			L	L	L	
56	Oxford Downs Cricket Club, Abingdon Road, Standlake. OX29 7QH	9	Cricket	Sport Club	One good quality cricket square with 15 grass wickets and a nonturf pitch. The square is played to capacity on Saturdays but has capacity on Sundays and midweek. Club need to expand changing facilities and car parking; need more permanent solution for ground as sharing facilities.	Sustain square quality through dedicated maintenance regime. Oxfordshire cricket to engage with Club to offer support.	Sport Club ECB/ OCB	Local Site	М	L	L	Protect
61	School Piece (Eynsham CC), Cassington Road, Eynsham. OX29 4LF	9	Cricket	Sport Club	One standard quality grass cricket square with ten grass wickets which is overplayed by six matches per season.	Improve square quality through enhanced maintenance regime to alleviate overplay.	Cricket ECB/ OCB	Local Site	М	S	L	Protect Enhance
70	Standlake Village Hall, Standlake. OX29 7SB	9	Tennis	Community	Three standard quality macadam tennis courts which are available to the community. Sportslighting in need of LED upgrade. Lower Windrush TC has plans to resurface the courts and build a clubhouse onsite and has funds available to do so. It believes if it could offer changing, toilet and refreshment facilities it would be able to attract more members.	Improve court quality through enhanced maintenance regime. Monitor Lower Windrush TC's growth and support the Club to remain within the recommended capacity. Support the club with LED upgrade to sportslighting.	Commu-nity LTA	Local Site	М	L	L	Protect Enhance
75	Tackley Village Hall Medcroft Road, Tackley. OX5 3AH	8	Football	Community Organisation	One standard quality adult 11v11 I pitch which is currently unused. It has one MES of actual spare capacity.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Commu-nity FF/OFA	Local Site	М	S	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
78	The Marlborough Church of England School, Shipton Road, Woodstock.	10	Football	School	Two youth 11v11, one youth 9v9, one mini 7v7 and two mini 5v5 pitches, all of standard quality. All pitch types have discounted spare capacity due to unsecure tenure.	Improve pitch quality through improved quality and increased regularity of maintenance. Develop a site wide multi-pitch community use offer for football, which takes in potential new 3G pitch and grass pitch provision.	School FF/OFA RFU LTA	Local Site (potential Hub Site)	М	S-M	L	Protect Enhance Provide
	OX20 1LP		3G pitch		Oxfordshire FA note previous discussions with the School regarding potential to develop a 3G pitch on the playing field. Woodstock Town FC has previously engaged with the School regarding a potential 3G facility, which could also be used by local club Stonesfield Strikers. Woodstock Town FC has potential to relocate to land directly east of the School site as part of proposals for alternative development of its existing site nearby. There is potential housing growth of c5,000 units by 2031 in Woodstock as set out in the WODC local plan.	Explore feasibility to develop a full size 3G pitch onsite to meet the identified Area 3G pitch shortfall for affiliated team training. Should a 3G pitch be developed, ensure the provider has in place a Pitch Replacement Fund for repair and resurfacing of a potential new 3G pitch when necessary. If a 3G pitch is developed onsite, ensure 3G registration is achieved and maintained so that the pitch can continue to support use for competitive match play. Improve quality and access to ancillary facilities to service a potential new 3G pitch if required.			Н	S	Н	
			Rugby Union		Two senior rugby union pitches of poor (M0/D1) quality. Pitches are played to capacity via curricular demand.	Improve pitch quality through enhanced maintenance regime.			L	L	L	
			Tennis		Four standard quality macadam tennis courts that are available for community use but without sports lighting. The courts are overmarked for netball.	Improve court quality through enhanced maintenance regime.			L	L	L	
90	Woodstock Bowls & Tennis Club Cadogan Park, Woodstock. OX20 1UW	10	Tennis	Sport Club	Four standard quality artificial surface tennis courts which are available for community use. Recently gained planning permission for sportslighting. The site is considerably overplayed by Woodstock TC but installation of sportslighting should help to alleviate this issue.	Improve court quality through enhanced maintenance regime. Explore options to increase court capacity onsite and reduce/alleviate overplay.	Sport Club LTA BE	Local Site	L	L	M	Protect Enhance Provide
			Bowls		One standard quality flat bowling green. Woodstock BC currently operates within the recommended site capacity although it is expected to exceed this after considering future demand.	Improve green quality through enhanced maintenance regime. Monitor future club growth to ensure increased demand does not cause green quality to deteriorate.			М	L	L	
91	Woodstock C Of E Primary School 2 Shipton Road,	10	Football	School	One mini 5v5 pitch of standard quality which is available for community use but has unsecure tenure.	Improve pitch quality through enhanced maintenance regime. Formalise community use agreement to provide users with security of tenure.	School FF/OFA	Local Site	М	S	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Woodstock. OX20 1LL											

Site ID	Site	IMD 10% bands (1 = most deprived	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
92	Woodstock Town FC New Road, Woodstock. OX20 1PD	10	Football	Sport Club/ Private	Two Adult 11 v 11 standard quality football pitches which are played to capacity by Woodstock Town FC, playing in the Oxford Senior League. Two men's teams and one Youth section use the pitches. The pitch is without sportslighting. Though managed by the Club via leasehold, the land is owned by Blenheim Estates which is understood to have proposals for alternative development of the site as residential. The current site is landlocked on four sides and offers little scope for expansion or improvement.	In the short-term, improve pitch quality through improved and more regular maintenance practices. Should a proposal come forward for development of the site for alternative use, ensure that appropriate mitigating reprovision is able to meet Sport England Playing Fields Policy and secured for the benefit of community sport. Explore options for relocation of the football club site and reprovision of grass pitch and ancillary facilities at land east of The Marlborough Church of England School, to develop a better quality facility able to accommodate future growth. OFA to encourage Club to undertake a Pitch Power assessment.	Sport Club Private FF/OFA	Local Site	Н	L	Н	Protect Enhance
93	Wootton War Memorial Playing Field	8	Football	Sport Club	One standard quality adult 11v11 football pitch which is overplayed by 0.5 MES per week.	Improve pitch quality through enhanced maintenance regime to alleviate overplay.	Sport Club FF/OFA ECB	Local Site	M	S	L	Protect Enhance
	Wooton Village, Boars Hill, Abingdon. OX1 5JL		Cricket		One standalone non-turf pitch.	Sustain wicket quality for recreational use.	ECB		L	L	L	
98	Bartholomew School, Bartholomew Close, Eynsham.	10	Football	School	One poor quality adult football pitch which is unavailable for community use. Request made by OFA to add pitch to Pitch Finder.	Improve pitch quality through enhanced maintenance regime.	School FF/OFA RFU	Local Site	L	L	L	Protect Enhance
	OX29 4QG		Rugby Union		One poor (M0/D1) quality senior rugby union pitch which is unavailable for community use. The pitch is played to capacity through curricular use.	Improve pitch quality through enhanced maintenance regime.			L	L	L	
101	Stanton Harcourt Cricket Club Steady's Lane, Stanton Harcourt. Witney. OX29 5RL	7	Cricket	Parish Council	One standard quality cricket square with six wickets. The square is overplayed by 12 matches per season. Landlord unwilling to provide long term lease which affects Club's ability to access funding. Square quality is said to have deteriorated in recent years and the Club struggles to provide good wickets every match. Club investigating feasibility of installing non-turf practice nets and increasing size of playing area from 6 to 8 wickets.	Improve wicket quality onsite to reduce overplay. Explore the feasibility of providing a non-turf pitch and additional wickets onsite to alleviate overplay. Support the Club to improve training facilities onsite.	Parish Council ECB/ OCB	Local Site	Н	M	M	Protect Enhance Provide

Witney

Site ID	Site	IMD 10% bands (1 = most	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
9	Burwell Recreation Ground, 465 Thorney Leys, Witney. OX28 5NR	g 9	Football	Parish/Town Council	Two standard quality adult 11v11 pitches. One is overmarked with a youth 9v9 pitch and the second is overmarked with two mini 7v7 pitches. The pitches are overplayed by 2.5 MES per week. Burwell Hall has 2 changing rooms, 4 showers and 2 toilets; the facility is in a poor condition. The Town Council had previously explored extending, external lockers and refurbishment with the ideal solution being to extend, however this was ruled out due to costs. The Town Council will look to identify the most economic and effective solution within their budget, including the use of s106 funding which has been allocated to the development of these facilities.	Improve pitch quality through enhanced maintenance regime to reduce overplay. Look to relocate some demand to an alternate site with spare capacity to alleviate overplay. Support the Town Council to provide dedicated ancillary provision onsite. OFA to encourage Town Council to undertake a Pitch Power assessment.	Town Council FF/OFA	Local Site	Н	S	Н	Protect Enhance Provide
37	Glebelands Playing Field, 10 Aston Road, Ducklington. OX29 7US	8	Football	Sport Club	One adult 11v11, one 9v9, two 7v7s and one 5v5 pitch all of good quality. The adult pitch is overplayed by two MES per week; the youth 9v9 pitch is played to capacity at peak time. Pitches are reported to drain poorly and an adult and a youth 9v9 pitch are overmarked on a cricket outfield. Ducklington FC states that ancillary provision onsite is in poor condition. The site is identified for pitch and ancillary improvements in the 2020 LFFP. Pitch Power Assessment last undertaken in 2023.	Improve pitch quality through enhanced maintenance regime to reduce overplay and in line with LFFP recommendations. Look to relocate some demand to an alternate site with spare capacity to alleviate overplay. Improve ancillary facility quality in line with 2020 LFFP recommendations.	Sport Club FF/OFA ECB/ OCB	Local Site	H	M	M-H	Protect Enhance
			Cricket		One good quality cricket square with eight grass wickets which is currently unused.	Sustain pitch quality through dedicated maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.			M	S	L	
40	Hailey C of E Primary School Middletown Grange, Witney. OX29 9UB	8	Football	School	One standard quality mini 7v7 pitch and one poor quality mini 5v5 pitch that are available for community use. The mini 7v7 pitch is played to capacity at peak time whilst the mini 5v5 pitch has discounted spare capacity due to unsecure tenure.	Improve pitch quality through enhanced maintenance regime. Look to formalise a community use agreement to provide Witney Vikings Youth FC with security of tenure.	School FF/OFA	Local Site	M	М	L	Protect Enhance
41	Hailey Recreation Ground Middle Town, Hailey, Witney. OX29 9UA	9	Football	Parish/Town Council	One standard quality adult football pitch with actual spare capacity of 0.5 MES per week.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA	Local Site	M	S	L	Protect Enhance
47	King George V Playing Field	9	Football	Parish/Town Council	One good quality adult 11v11 football pitch which has actual spare capacity of 0.5 MES per week.	Sustain pitch quality through dedicated maintenance regime.	Council FF/OFA	Local Site	L	S	L	Protect

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
	Newland, Witney. OX28 3JN					Maximise spare capacity to alleviate overplay of other pitches in the area.						
51	51 Leys Recreation Ground, Station Lane, Witney. OX28 4BX	4	Football	Parish/Town Council	One poor quality adult 11v11 pitch and two youth 9v9, two mini 7v7 and one mini 5v5 pitch all of good quality. The adult pitch is played to capacity whilst the mini 5v5 pitch is played to capacity at peak times. The youth 9v9 and mini 7v7 pitches each have actual spare capacity of one MES per week. The adult pitch onsite is used as an event field, is too compacted for football use and can no longer be used for football. Spartan Rangers FC previously used this pitch and are temporarily using alternative sites until a new site is found. Onsite ancillary provision is very dated and in poor condition. New development Courtside at The Leys (23/02731/FUL) received planning permission early 2024 to create new changing rooms, enhanced ancillary and sporting facilities; due for completion Nov 2024.	Improve pitch quality through enhanced maintenance regime. Ensure that an alternate pitch is provided for Spartan Rangers FC now that the adult pitch is no longer available. Support provision of new ancillary facilities onsite.	Town Council FF/OFA ECB/OCB BE Parks Tennis LTA	Key Centre	М	S	L	Protect Enhance
			Cricket		One standard quality grass cricket square with six wickets that had not been used since 2020. In March 2024, Witney Town Council agreed Cricket can recommence at the Leys; will monitor usage by cricket.	Improve square quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.			M	S	L	
			Bowls		One good quality flat bowling green used by Witney Town BC.	Sustain green quality through dedicated maintenance regime.			L	L	L	
			Tennis		New development, Courtside at The Leys (23/02731/FUL), due to be completed by Nov 2024. Will provide 4 x tennis courts, 3 x Padel courts and a MUGA. Some canopy provision and sportlighting will be provided. Although this is a reduction in tennis courts (from 7 to 4) this is supported by the LTA.	Improve court quality through enhanced maintenance regime.			L	L	L	
New entry	Deer Park Recreational Ground, Valence Crescent, Witney. OX28 5GB		Football	Parish/Town Council	Not included in Feb 22 PPS report. Site had two adult pitches which had not been used for some time and were in poor condition. Considered that site only suitable for one full sized adult 11v11 pitch. One pitch was remediated by WODC in May 2024; now await line marking and goals to be erected and once complete will be transferred to WTC and Priority reduced to Low.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA	Local Site	M	L	L	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
58	Ralegh Crescent Park, Witney. OX28 5GP	10	Football	Parish/Town Council	One standard quality youth 9v9 pitch with one MES of actual spare capacity. This previously unused, pitch was in poor condition and was remediated by WODC in May 2024; now await line marking and goals to be erected and once complete will be transferred to WTC and Priority reduced to Low.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA	Local Site	M	L	L	Protect Enhance
65	South Leigh Recreation Ground Station Road, South Leigh, Witney. OX29 6XN	5	Football	Parish/Town Council	One standard quality adult 11v11 football pitch which is currently unused and has one MES of actual spare capacity.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Council FF/OFA	Local Site	M	S	L	Protect Enhance
76	The Henry Box School, Playing Fields Ducklington Lane, Witney. OX28 4JP	4	Football	School	Two standard quality adult 11v11 football pitches which are available to the community but have discounted spare capacity due to unsecure tenure.	Improve pitch quality through enhanced maintenance regime.	School FF/OFA RFU	Local Site	L	L	L	Protect Enhance
			Rugby Union		Two senior rugby union pitches of poor (M0/D1) quality. The pitches are played to capacity via curricular demand.	Improve pitch quality through enhanced maintenance regime.			L	L	L	
77	The King's School New Yatt Road, Witney. OX29 6TA	8	Football	School	One youth 9v9 and one mini 7v7, both of standard quality. Both pitches have discounted spare capacity due to unsecure tenure.	Improve pitch quality through enhanced maintenance regime.	School FF/OFA	Local Site	L	L	L	Protect Enhance
83	Wash Meadow, Minster Riding, Minster Lovell. OX29 0RN	9	Football	Trust	One standard quality adult 11v11 football pitch with actual spare capacity of one MES per week.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. OFA to encourage Trust/Club to undertake a Pitch Power assessment.	Trust FF/OFA ECB/ OCB	Local Site	М	S	L	Protect Enhance
			Cricket		One good quality cricket square with 16 grass wickets. Played to capacity at weekends but spare capacity during the week.	Sustain square quality through dedicated maintenance regime.			L	L	L	

Site Site ID	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
84 West Witner Sports Ground, Burford Roa Witney. OX29 0NB	10	Football Cricket	Parish/Town Council	One adult 11v11, three youth 9v9 and one 7v7 all rated as good quality; One adult and one, mini 5v5 pitches, all rated as poor quality. Marked onto playing field area serving as cricket pitch outfield. Pitches mainly used by Tower Hill FC. The adult pitches are overplayed by 3.5 MES per week whilst 9v9 pitches are played to capacity. The 7v7 pitches are played to capacity at peak time whilst the 5v5 pitches have discounted spare capacity due to poor pitch quality. Pitches onsite are well maintained by the Town Council but suffer heavily from unofficial use, wildlife damage and dog fouling. A section of the playing field drains poorly and in adverse weather conditions, both adult and 9v9 pitches can be unusable over the winter months. Tower Hill FC aspires to improve drainage and create a training facility with sportslighting onsite. One good quality cricket square with 14 grass wickets. Played to capacity on Sundays but has additional capacity on Sundays and midweek. Used by Witney Swifts CC which has a pay and play agreement for the site; Club working with Witney Town Council to agree a long-term lease/agreement or be part of a management Trust, as well as taking on additional maintenance responsibilities for the cricket provision. The clubhouse has been closed to the public having fallen into a state of disrepair. Tower Hill FC uses shipping containers for storage onsite and temporary toilet facilities have been provided by the Town Council whilst the clubhouse is inaccessible. Witney Swifts CC players have no access to dedicated toilets, instead using toilet facilities in the bar area. Planning application (23/02574/FUL) approved to refurbish existing sports clubs to include updates to social space, changing rooms, toilets etc. Pitch Power Assessment last undertaken in 2024. Four standard quality macadam tennis courts (repainted in 2022) that have sportslighting and available for community use.		Town Council FF/OFA ECB/ OCB LTA BE	Key Centre (potential Hub Site)	H	S-M	H	Protect Enhance Provide

27

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
					Discussions ongoing between Witney LTC and Witney Town Council re establishing a long-term lease agreement to attract grant funding and improve the facilities onsite.							
84	West Witney Sports Ground, Burford Road, Witney. OX29 0NB	10	Bowls	Parish/Town Council	One good quality flat bowling green used by Witney Mills BC and West Witney BC. Witney Mills BC only has access to changing facilities alongside the green at West Witney Sports Ground and so is without clubhouse, toilet or shower facilities. West Witney BC aspires to form a long-term lease agreement with Witney Town Council to attract grant funding.	Explore options for an alternative governance model which secures long-term tenure for the sports clubs onsite and promotes multi-partner responsibility, rather than individual long-term leasehold arrangements. This could potentially be through development of a new Trust-led model or sports association, with representation from each of the resident user clubs.	Town Council FF/OFA ECB/ OCB LTA BE	Key Centre (potential Hub Site)	Н	S-M	Ħ	Protect Enhance Provide
85	Witney Artificial Turf Pitch Gordon Way, Witney. OX28 4EH	4	3G pitch	Leisure Trust	One good quality full size FIFA approved 3G pitch which has sports lighting and available for community use. Although the pitch is supported by four changing rooms with showers and toilets, due to significant water damage in Dec 2022, these changing rooms are unusable. A staged approach to repair work is planned with 2 changing rooms to be ready by Autumn 2024, other works to be undertaken thereafter. There is also a meeting room and a kitchen. The pitch is played to capacity, with very limited availability.	Sustain pitch quality through a high quality and dedicated maintenance regime. Ensure repair works to changing rooms are undertaken. Ensure the provider (WODC) has in place a Pitch Replacement Fund, formed over time, for repair and resurfacing when necessary (as per Football Foundation Terms & Conditions). Ensure 3G registration is renewed when required so that the pitch can continue to support use for competitive match play.	Leisure Trust FF/OFA	Local Site	M	М	Н	Protect Enhance
86	Witney Mills Cricket Club, Newland,	9	Football	Sport Club	One standard quality adult 11v11 football pitch with 0.5 MES of actual spare capacity.	Improve pitch quality through enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area.	Sport Club FF/OFA ECB/	Local Site	М	S	L	Protect Enhance
	Witney. OX28 3JD		Cricket		One good quality cricket square with 12 grass wickets which is played to capacity at weekends but has capacity during the week. Height of roadside cricket fencing needs to be increased and Club also has a project for 3 new covered practise nets.	Sustain square quality through dedicated maintenance regime. Support the club to improve provision onsite.	OCB		M	M	M	
87	Witney Rugby Club, Hailey Road, Witney. OX29 9UH	8	Rugby Union	Sport Club/ Private	Five senior, four junior and six mini pitches, all good (M2/D1) quality. Two senior pitches have sportslighting, both overplayed by 1.5 MES per week due to the training and match play demand, whilst all remaining pitches have actual spare capacity. The main parcel of land at Witney Rugby Club has four senior pitches with the clubhouse, owned by the Club. It rents the adjacent field from a local farmer, on which several pitches are	Sustain pitch quality through dedicated maintenance regime. Explore the feasibility of Witney RFC and Witney HC's joint aspirations to further develop and reconfigure Witney Rugby Club to service both clubs. Consider the feasibility of providing a 3G rugby compliant hybrid pitch on site, should pilot projects prove hybrid pitches to be beneficial for rugby union.	Sport Club Private RFU EH	Local Site (potential Key Centre)	M	M-L	H	Protect Enhance Provide

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
					marked, mainly junior and mini sizes. This adjacent land offers unsecure tenure as no formal agreement is in place, although Witney Town Council has designated the field for sporting use only. The site is supported by good quality ancillaries, and the Club have undertaken a significant social space improvement constructing a large extension and will be improving its patio area etc, through the Impact 25 programme and joint funded by RFU and WRFC. This will affect the club and whole membership moving forwards, enabling it to facilitate the growth of female participation. The Club is classed as a full house club offering rugby at all ages; both male and female activity takes place on the site. Witney RFC has future aspirations for a two storey clubhouse development to incorporate use by Witney Hockey Club. Any intensification of the site (Hockey) would need some very careful consideration and significant s106 investment.	Consider whether the Club could utilise s106/CIL funding for improvements due to considerable local housing growth.						
88	Wood Green School, Woodstock Road, Witney. OX28 1DX	9	Rugby Union	School	Two senior rugby union pitches of poor (M0/D1) quality that are overmarked on a cricket outfield. Pitches are played to capacity through curricular use. School keen to create a Sports Hub and willing to have a 3G football pitch located at their site.	Improve pitch quality through enhanced maintenance regime. Should a 3G pitch be developed, ensure the provider has in place a mechanism for future sustainability, such as a pitch replacement fund formed over time, for repair and resurfacing of a potential new 3G pitch when necessary. If a 3G pitch is developed onsite, ensure 3G registration is achieved so that the pitch can continue to support use for competitive match play. Any 3G pitch should have with sportslighting to meet the Area 3G pitch shortfall for affiliated football team training. Ensure that a new 3G pitch does not negatively impact on grass sports provision at the school.	School RFU RFL EH LTA	Hub Site	L	L	L	Protect Enhance Provide
			Rugby League		Rugby Union pitches mentioned above are used by West Oxfordshire Levellers RLFC for rugby league demand through the summer and remain played to capacity.	Improve pitch quality through enhanced maintenance regime.			L	L	L	
			Hockey Sand based		One full size hockey suitable AGP which is has sportslighting and available for community use. The pitch	Retain the AGP as a sand based surface and the key facility to meet			Н	S	Н	

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
			AGP		is in poor condition after being built c2004. Witney HC reports the subsurface shock absorber has now disintegrated. EH indicates the surface should have been replaced around 2020, that sportslighting levels onsite are poor, meaning late afternoon/evening fixtures may be unable to be safely played. Requirement to upgrade sportslighting to LED. In March 2024, School committed to undertaking the required ATP recarpeting works which will now be undertaken summer 2024. School keen to work with HC to arrange long term lease. Witney HC are keen to build a clubhouse which the School and other sports users could use; fundraising is underway. The HC currently uses changing provision at the School, but return to Witney Rugby Club as a postmatch facility for social provision.	hockey demand in the District for the long-term. Support the School to resurface the pitch as a priority and replace/improve sports lighting with LEDs. Ensure the provider (Wood Green School) has in place a mechanism for future sustainability, such as a pitch replacement fund, formed over time, for repair and resurfacing when necessary. Seek to formally secure long-term access for hockey, both for training and weekend matches. This could form a condition as part of the transition of affiliated football team training from this Hockey site to a new 3G pitch in Witney. Capacity released from the programme of use through this transfer should be prioritised to ensure hockey demand is met in the first instance. Consider relocation of Wychwood HC to this site for the long-term (matches and training) if it means hockey use can be secured.						
			Tennis		Six standard quality macadam tennis courts which are available for community use but without sportslighting. The courts are overmarked for netball.	Improve court quality through enhanced maintenance regime.			L	L	L	
89	Wood Green Playing Fields, (Madley Park Football pitch and grounds) Witney. OX28 1AR	9	Football	Parish/Town Council	Two poor quality youth 11v11 pitches which are currently unused, providing two MES of actual spare capacity. Possible location for 3G pitch and Wood Green School's preferred site.	If site not used for 3G pitch, improve pitch quality through specific remediation and then an enhanced maintenance regime. Maximise spare capacity to alleviate overplay of other pitches in the area. Should a 3G pitch be developed at this location, ensure the provider has in place a mechanism for future sustainability, such as a pitch replacement fund formed over time, for repair and resurfacing of a potential new 3G pitch when necessary. If a 3G pitch is developed onsite, ensure 3G registration is achieved so that the pitch can continue to support use for competitive match play. Any 3G pitch should have with sports lighting to meet the Area 3G pitch shortfall for affiliated football team training. Ensure that a new 3G pitch does not negatively impact on grass sports provision at Wood Green School.	Council FF/OFA	Local Site	M	S	М	Protect Enhance

Site ID	Site	IMD 10% bands (1 = most deprived)	Sport	Management	March 2024 Status	June 2024 Recommended actions	Partners	Site hierarchy tier	Priority	Timescale	Cost	Aim
New	Windrush Place Pitches, Centenary Way, Witney. OX29 7AR		Football	WODC	Two Adult 11v11 pitches due to become available Summer 2025 along with a new Sports Pavilion and Polymetric playzone for community use. To be transferred from WODC to WTC on completion.	-	Council FF/OFA	Local Site	-	-	1	Protect Provide

WEST OXFORDSHIRE PLAYING PITCH STRATEGY & ACTION PLAN